

Measurements, observations (1-1)


errors: Random
Systematic
gross (blunders)

Systematic Errors

compensate by correction
add parameters to model (self-calibration)
design instrument or meas. plan to eliminate

Aug 22-9:59 AM

examples leveling (1-2)



Aug 22-9:58 AM

gross-blunders
other criteria for adjustment
L1-norm

IRLS

all techniques LOTS OF REDUNDANCY

Random Errors

1-3

Aug 22-9:58 AM